

General Environmental Incident Summary

Incident: 5226 **Date/Time Notice:** 9/14/2016 0815 **DEM Incident No:**

Responsible Party: Plains Midstream Canada

Date Incident: 9/13/2016 **Time Incident:** 2245 **Duration:**

County: Williams **Twp:** 155 **Rng:** 103 **Sec:** 21 **Qtr:**

Lat: 48.22760 **Long:** -103.94150 **Method:** Interpolation from map

Location Description: Stateline Plant
15071 56th Street NW
Williston, ND 588011

Submitted By: Levi Weltikol

Affiliation:

Address: 896 25th St SE

City: Sidney

State: MT

Zip: 59270

Received By:

Contact Person: Jeff Schumack
325 McDonald Street North
Regina , SK

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Truck tank overflow

Description of Released Contaminant: natural gas condensate

Volume Spilled: 10.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Overfilled front compartment

Risk Evaluation:

No immediate risk

of Fatalities:

of Injuries:

Affected Medium: 03 - soil

Potential Environmental Impacts:

The spill was minor and isolated in size. Impact appears to be limited to the immediate surface soils. No long term impacts anticipated.

Action Taken or Planned:

Buckets were put in place to prevent any more product to hit the ground. soil was excavated and drummed for future removal. No further action is planned.

Wastes Disposal Location: Certified landfill

Agencies Involved:

Updates

Date: 9/14/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, 10 gallons of natural gas condensate were released onto the immediate surface soils of the ONEOK Stateline Plant facility. Due to the low volume of the release and procedures needed to enter these facilities, this incident will be added to the quarterly or semi-annual inspection list for further follow-up. Further follow-up needed.

Date: 11/3/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Volume:

Notes:

Site will be inspected during quarterly site visits.